

experience has shown that the Beaver's flat bottom wing does not respond all that well to ailerons. It flies just fine on rudder only.

Add fuel proofer to the firewall and sheeting, then cover with Monocoat or a covering of your choice. The tail section did not require any additional modifications or sheeting beyond adding hinges for the rudder and elevator. To connect the elevator halves, I used a 1/8" diameter music wire formed in a flat U.

Hope this helps. If you need any sketches, just give me a call. I will be sending construction pictures of the Hawker Hurricane soon.

Your friend in the frozen tundra,

*Gene Turk*

Gene Turk

920-922-5511